



Hewlett-Packard Company
1501 Page Mill Road
Mail Stop 510101
Palo Alto, CA 94304
www.hp.com

Walter Overcash
Product Regulatory Engineer
281.514.2756 Tel
walter.overcash@hp.com

October 30, 2014

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

Dear Sir:

In accordance with §15.407(i), we acknowledge that should any harmful interference be generated to licensed services in 5.15-5.25 GHz by FCC ID: B94HNQ91CHWFTWN, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

If you have any comments or questions, please feel free to contact me.

Sincerely,

Walter Overcash
Walter Overcash