



Appendix D. Product Photos

Please refer to Sporton report number EP092732 as below.

Appendix E. Test Setup Photos



Front Face of the DUT with Phantom 10 mm Gap



Rear Face of the DUT with Phantom 10 mm Gap



Right Side of the DUT with Phantom 10 mm Gap



Left Side of the DUT with Phantom 10 mm Gap



Top Side of the DUT with Phantom 10 mm Gap



Bottom Side of the DUT with Phantom 10 mm Gap