



561F Monterey Road
Morgan Hill CA 95037
Tel:(408)463-0885,Fax: (408)463-0888

Federal Communications Commission
Equipment Authorization branch
7435 Oakland Mills Road
Columbia, MD 21046

Attn: reviewer

Re: Request for 731 form(DTS portion)correction

SUB: Applicant: LG ELECTRONICS INC.
FCC ID: BEJTBLT20A, Form 731 confirmation#: EA843464

We uploaded the above submission for LG on March 10,2005.

We revised DTS report on March 11, 2005
Please kindly help us to correct Rated RF power output data in 5745-5825 MHz .

The original 5745-5825 MHz technical entry is: 0.18621W.

The correct 5745-5825 MHz technical entry should be: 0.20893 W.

Due to the output power correction, we uploaded a revised DTS report, please review the new attachment **05I3251-1 FCC DTS Report(revised 3-11,no setup photos).pdf**, please do not review attachment **05I3251-1 FCC DTS Report(no setup photos).pdf**

Your prompt attention to this matter will be highly appreciated.

Sincerely Yours,

Claire Hoque
Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037
Tel: (408) 463-0885 x 123
Fax: (408) 463-0888