


FCC ID: BEK9E3UBT

8-30-2010

Federal Communications commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia MD 21046

I would like to confirm this device (FCC ID: BEK9E3UBT) does not have tune up information because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Sincerely,

A handwritten signature in black ink, appearing to read "John Nady", is written over a horizontal line.

Signature

Jonn.Nady / President

Phone: 510 652-2411
Fax: 510 652-5075
Address : 6701 Bay Street Emeryville, California 94608, U.S.A.