

CHANGES ON TABLE 2.4-1 OF 2.983(d)(6)

REF	DESC	MANUFACTURER	FUNCTION
IC710(DELETE)	CXG1013N	SONY	RX FRONT END
TR731(DELETE)	3SK309XV	HITACHI	RX FRONT END
IC740(DELETE)	NJG1551F	JRC(SHIN)	RX FRONT END
IC750(DELETE)	SPM3252	SANYO	RX FRONT END
IC701(ADD)	MC13740	MOTOROLA	RX FRONT END
IC760(DELETE)	TA31136FN	TOSHIBA	RX BACK END
IC780(DELETE)	AD607ARS	ANALOG DEVICES	RX BACK END
IC860(DELETE)	MB15S91PFV	FUJITSU	RX BACK END
IC870(DELETE)	MB15S91PFV	FUJITSU	RX BACK END
TR860(DELETE)	UMX5N	ROHM	RX BACK END
IC702(ADD)	RKS-5PF3086	AKM	RX BACK END
IC930(DELETE)	CMM1333	CELERITEK	PA
IC960(DELETE)	MRFIC0913R2	MOTOROLA	PA
IC930(ADD)	MRFIC1856	MOTOROLA	PA
IC950(OLD)	FMM5020MUT	FUJITSU	LB DRIVER
IC950(NEW)	UPG173TA	NEC	LB DRIVER
IC920(OLD)	FMM5022MUT	FUJITSU	HB DRIVER
IC971(NEW)	UPG174TA	NEC	HB DRIVER
IC900(OLD) MODULATOR/VGA	ATTW2013CBY	ATT&T/LUCENT	
IC900(NEW) MODULATOR/VGA	W3013	LUCENT	
IC980(DELETE)	M62261FP	MITSUBISHI	NEGATIVE
IC981(DELETE)	TA75S01F	TOSHIBA	BIAS
IC960(ADD)	MAX1721	MAXIM	GENERATOR
IC810(DELETE)	LMX2331LTMX	NS	PLL
IC821(DELETE)	TC7S66FU	TOSHIBA	PLL
IC860(ADD)	LMX2352	NS	PLL
TR830(OLD)	2SC4784	HITACHI	LO BUFFER AMP
IC850(NEW)	UPC8151TB	CEL	LO BUFFER AMP
TR840(OLD)	3SK309XV	HITACHI	LO BUFFER AMP
IC810(NEW)	UPC8151TB	CEL	LO BUFFER AMP
IC830(NEW)	UPC8151TB	CEL	LO BUFFER AMP

The reason for these changes is the lower cost of these particular parts. These parts were chosen so we can meet the original MT253 specifications. No RF characteristics or specifications has changed.