

Horizon Hobby, LLC

2904 Research Rd. Champaign, Illinois 61822, United States

Attestation Statements

To: Federal Communications Commission

Date: Jun. 19, 25

7435 Oakland Mills Road,

Columbia, MD 21046, USA

Subject: Attestation of Compliance with FCC Covered List Software Requirements

FCC ID: BRWTRI2021

Product Name: OTA Wireless programmer

This letter serves as an attestation that the equipment identified above ☐ **is** / ☒ **is not** (select one) "covered" software as defined under the Federal Communications Commission (FCC) Covered List requirements, as outlined in **FCC 22-84** and **KDB 986446**.

Specifically, the undersigned certifies that the equipment for which authorization is sought:

1. **Does not contain** cybersecurity or anti-virus software produced or provided by **Kaspersky Lab, Inc.** or any of its successors, assignees, parents, subsidiaries, affiliates, or any entity that has rebranded or relabeled software produced by the aforementioned entities.
2. **Does not have the capability** to store, run, or deliver any software identified on the FCC Covered List, including but not limited to cybersecurity and anti-virus software.

To support this attestation, the appendix evaluation documentation has been prepared and is included in the certification filing.

This attestation is based on a thorough evaluation of the device's design, functionality, and software environment. The undersigned affirms that the information provided is accurate and complete to the best of

their knowledge.



Name/Title :	Jason Rosa/Lead Quality and Compliance Associate
Company:	Horizon Hobby, LLC
Address:	2904 Research Rd. Champaign, Illinois 61822, United States
Phone:	217-403-3218
Fax:	217-403-3672
E-Mail:	compliance@horizonhobby.com

Horizon Hobby, LLC

2904 Research Rd. Champaign, Illinois 61822, United States

Evaluation regarding to the Covered List Software:			
Compliance Methodology	Evaluation Process		Results
Device is Inherent compliance	☒	The Chipset(s) used is limited to run the Cybersecurity or anti-virus software.	The RF chip " FR8016" don't support the mentioned function.
	☐	The Memory used is limited to run the Cybersecurity or anti-virus software.	
	☐	There is storage capacity limitation for store or install the Cybersecurity or anti-virus software.	
	☐	Operating system used is limited to run, install or deliver the Cybersecurity or anti-virus software.	
Device is not Inherent compliance	☐	Evaluation Based on Software Bill of Materials (SBoM)	
	☐	Evaluation Based on Scan for Software on the device	
	☐	Evaluation Based on Filesystem scan	
	☐	Evaluation Based on Running software check	