TriGem Computer, Inc.

Date: 2009.10.14

Compliance Certification Services Certification Division 561F Monterey Road Morgan Hill, CA 95037

To whom it may concern:

There are two modifications in internal photo.

First, it is part to be connected connector of sub LCD PCB and Pin in 3 page of internal photo.

Second, it is main PCB part in 22 page of internal photo.

These connected lines were modified to improve touch functions by our Trigem laboratory.

These modifications will be improved at the production line hereafter.

Sincerely Yours,

SO Shim - Product Manager **TG TriGem Computer, Inc**