

SECTION 2.1033 (c) and Part 15.21

SECTION 2.1033 (c) Label and label location - A photo showing the identification label clearly (you must be able to see the name and FCC ID number), and the location on the device. In lieu of a photo for this, you may submit a engineer's drawing.

Part 15.21 Statement - for all intentional and unintentional radiators is also printed on the label. All devices shall bear the following statement in a conspicuous location on the device:

" This device complies with Part 15 of the FCC Rules Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. "

THE ENGINEERS DRAWING:

**Honeywell**

MODEL NO. 5808W3XT  
SMOKE DETECTOR/TRANSMITTER

**FCC ID: CFS8DL5808W3XT**  
IC: 573F-5808W3XT  
IC MODEL: 5808W3XT

**S911 SIGNALING**  
**UL LISTED**

SMOKE-AUTOMATIC FIRE DETECTOR WITH INTEGRAL AUDIBLE SIGNAL AND HEAT DETECTOR FOR OPEN AREA PROTECTION. FIRE ALARM EQUIPMENT ISSUE NO. A-48,199

WARNING: REPLACE BATTERY WITH A PANASONIC CR123A, ADEMCO 466, DURACELL DL123A, OR SANYO MODEL CR123A ONLY. WAIT 10 SECONDS AFTER REMOVAL OF OLD BATTERY BEFORE INSERTING NEW BATTERY. USE OF ANOTHER BATTERY MAY PRESENT RISK OF FIRE OR EXPLOSION. SEE OWNER'S MANUAL FOR SAFETY PRECAUTIONS.

PHOTOELECTRONIC DETECTION PRINCIPLE AND 135°F (57°C) THERMAL

MAXIMUM INSTALLATION AMBIENT TEMPERATURE 100°F (37.8°C)

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.

U.S. PAT: 5,004,999, 5,155,469, 5,831,524, 6,445,292, 6,521,907, 6,577,242, 6,084,522, 6,222,456, 7,120,795

MAINTENANCE: DISABLE THE SYSTEM, OPEN THE DETECTOR, AND CLEAN THE CHAMBER. SEE D100-100-00 FOR DETAILED INSTALLATION AND MAINTENANCE INSTRUCTIONS.

SENSITIVITY RANGE 1.0-4.0%/FT

FOR REPAIR, RETURN TO:  
HONEYWELL  
12220 ROJAS DRIVE  
SUITE 700  
EL PASO, TX 79936

MADE IN MEXICO

????  
N04-4489-000

EXACT LOCATION OF THE LABEL ON THE BACK PLASTIC:

