



Tim Dwyer <rfspectrum@gmail.com>

answer: 09U12936 TCB questions: Toshiba Corporation, FCC ID: CJ6UPLL3APC, Assessment NO.: AN09T9932, Notice#1

1 message

Claire Hoque <claire.hoque@ccsemc.com>

Fri, Dec 11, 2009 at 1:25 PM

To: Tim Dwyer - TCB <Timothy_Dwyer@ieee.org>, "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>
Cc: Tina Chu <tina.chu@ccsemc.com>

Hi Tim,

Q1: Co-located WLAN and BT modules are described and evaluated in the SAR report. The evaluation is ok, but I do not see the FCCID of the WLAN and BT modules. Please provide the FCCID's for the modules.

[Answer]WLAN and BT modules FCC IDs were stated on the attached MPE calculation report.

Q2: Please describe how Toshiba will address compliance for the co-located modules in the Netbook platform (Composite filing, modular procedures, etc) and describe how the product will be labelled.

[Answer]colocated modules have been addressed through modular approvals changed. When the wlan and BT is installed inside, host label will indicate "Contains FCC ID:XXXXXXX".

Q3: The product label does not show DoC markings although the user manual indicates DoC compliance. Please provide a revised label or statement confirming that the grantee will affix the appropriate label and label information for DoC.

[answer] Will the revised label with DoC logo later.

Thanks.

Claire

-----Original Message-----

From: Claire Hoque
Sent: Thursday, December 10, 2009 5:06 PM
To: Thu Chan; Tina Chu; Sunny Shih
Subject: 09U12936 TCB questions: Toshiba Corporation, FCC ID: CJ6UPLL3APC, Assessment NO.: AN09T9932, Notice#1

Hi All,

Pls answer TCB questions below.
Thanks,

Claire Hoque
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538, USA
Tel: (510) 771-1123
Fax: (510) 661-0888

-----Original Message-----

From: Timothy M. Dwyer
Sent: Thursday, December 10, 2009 5:02 PM
To: Thu Chan; Claire Hoque
Cc: Timothy M. Dwyer
Subject: Toshiba Corporation, FCC ID: CJ6UPLL3APC, Assessment NO.:

Hi Claire, Thu,

This notice is being sent prior to completion of the review to provide time to obtain needed information. If there are additional issues, they will be sent in separate notices.

Q1: Co-located WLAN and BT modules are described and evaluated in the SAR report. The evaluation is ok, but I do not see the FCCID of the WLAN and BT modules. Please provide the FCCID's for the modules.

Q2: Please describe how Toshiba will address compliance for the co-located modules in the Netbook platform (Composite filing, modular procedures, etc) and describe how the product will be labelled.

Q3: The product label does not show DoC markings although the user manual indicates DoC compliance. Please provide a revised label or statement confirming that the grantee will affix the appropriate label and label information for DoC.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical reviewer

 [09U12936-1 FCC IC RF Exposure Report_Final.pdf](#)
153K
