



October 24, 2023

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Re: Applicant: Physio-Control, Inc.
FCC ID: CZO23LP35
Part 2.933(b) Change in Identification of Equipment

Physio-Control, Inc. requests a change in identification of a currently certified device under Part 2.933(b).

The original equipment identification is FCC ID: Z64-WL18DBMOD.
The original Grantee: Texas Instruments Incorporated was granted approval on 12/24/2014.

The original test data filed by Texas Instruments Incorporated continues to be representative of the newly identified device. There are no changes to the hardware or software.

This change in identification is requested for the newly identified device, FCC ID: CZO23LP35, which is physically and electrically identical as defined by Part 2.907, to the originally approved module.

Photographs as required under Part 2.933(5) and FCC ID label are submitted with this request.

Please let us know if you might require anything further to assist with your review of this Change in Identification of Equipment.

Thank you,

Timothy Rand
Sr Compliance Standards Engineer
Stryker Emergency Care
11811 Willows Rd NE
Redmond WA 98052
+1 425 867 4477
tim.rand@stryker.com
www.physio-control.com

Emergency Care

11811 Willows Road NE, Redmond, WA 98052 USA | P +1 425 867 4000 | Toll-free +1 800 442 1142 | stryker.com