


INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)




INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)



INTERTEK TESTING SERVICE

Report No.: 17121176HKG-002

Equipment Photographs

(Internal)

