


EMC Technologies Report Number: M050532_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)



Harmonics – Channel 36

Ref Lvl	Marker 1 [T1]	RBW	1 MHz	RF Att	30 dB
15 dBm	5.52 dBm	VBW	1 MHz		
	5.14228457 GHz	SWT	600 ms	Unit	dBm




Date: 5.JUN.2005 15:15:23




Harmonics - Channel 52

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 9.10 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 600 ms Unit dBm



Date: 5.JUN.2005 15:18:13




Harmonics - Channel 64

Date: 5.JUN.2005 15:20:03



Harmonics - Channel 42 (Turbo)

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 3.19 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 600 ms Unit dBm




Date: 5.JUN.2005 15:30:40



Harmonics - Channel 50 (Turbo)

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 1.66 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 600 ms Unit dBm




Date: 5.JUN.2005 15:28:16



Harmonics - Channel 58 (Turbo)

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 6.89 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 600 ms Unit dBm



Date: 5.JUN.2005 15:26:03

