
Appendix C. Photographs of Setup

Conducted Emission

Mode 1, 3



FRONT VIEW



REAR VIEW

SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: EUNHXD8V2 Page No. : C1 of C4
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01

Report No.: FR791006



SIDE VIEW

Mode 2



FRONT VIEW

SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: EUNHXD8V2 Page No. : C2 of C4
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01







REAR VIEW



SIDE VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: EUNHXD8V2 Page No. : C3 of C4
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01

Report No.: FR791006

Radiation Emission

Mode 1-6



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: EUNHXD8V2 Page No. : C4 of C4
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01