



INTERTEK TESTING SERVICES



Internal photos

Handset





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 16070222HKG-001
FCC ID: EW780-0357-00
IC: 1135B-80035700



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



INTERTEK TESTING SERVICES



Internal photos

Base Unit




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

