



# INTERTEK TESTING SERVICES

---

## Internal photos







# INTERTEK TESTING SERVICES



---

## Internal photos



# INTERTEK TESTING SERVICES


## Internal photos



# INTERTEK TESTING SERVICES

---


## Internal photos



## INTERTEK TESTING SERVICES



---

### Internal photos



# INTERTEK TESTING SERVICES

## Internal photos





Test Report Number: 16040719HKG-001  
FCC ID: EW780-0381-00  
IC: 1135B-80038100

# INTERTEK TESTING SERVICES



---

## Internal photos



# INTERTEK TESTING SERVICES



## Internal photos



Test Report Number: 16040719HKG-001  
FCC ID: EW780-0381-00  
IC: 1135B-80038100

# INTERTEK TESTING SERVICES

## Internal photos







# INTERTEK TESTING SERVICES

---

## Internal photos







# INTERTEK TESTING SERVICES

---

## Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos

