



INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 18121235HKG-001
FCC ID: EW780-1553-00
IC: 1135B-80155300

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 18121235HKG-001
FCC ID: EW780-1553-00
IC: 1135B-80155300

INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

