

5.8G ip-8100-2 VoIP
35-005802-000-000

PRC01A
>PF-LP<

ESD Board
35-005809-000-000
PRC01B
>PF-LP<

HR_DS_DS-1187A
TY-F10
94V-0
100%
100%

TX_N
TX_P

RESET

RESEND
CONSOLE_TX
CONSOLE_RX

CND
I2C
I2D


TMS
TCK
TDI
TDO
3V2

LED1

LED2

PAGE

MAX
SCA



M2
0449

2.4GHz/3.5GHz: HFRM00 - c/d/ Rev. 1
using at 3824 IPIC
35-00582-000-000 Rev-1
3D-QW-C PWC 01.0

CAS_FSK
U1
VDDC
CID_P
CID_N
RX_P
RX_N
TX_N
TX_P
2V5
5.8G ip-8100-2 VoIP
>PF-LP<
PRC01A
35-005802-000-000


94V-0

94V-0 D4
CN_SM_R8785E

4804

4

LED2
LED1
RF_CLK
RDATA
TGFSK
CONSOLE_RX
CONSOLE_TX
I2D
I2C
GND
ST_LED1
ST_LED2
TEL_HK_SW
5V1
RESET
VTAM_PWR




M2 0449

2402Z/3202Z HYBRID - 6/6d Bussini
35-005802-000 Rev-1
3P-014-130 013

B5101V
U1
CAS_FSK
U2
VDDC CID_P
CID_N
RX_P
RX_N
TX_N
TX_P
5.8G ip-8100-2 VoIP
>PF-LP<
PRC01A
35-005802-000-000

94V-0
CN-SH-RB785E
4804
4

WARNIN
FIRE OR
MAKE S
SCARBY



2.4GHz/5.8GHz HYBRID - c/ci Bundle
using uL 5824 UPC
35-00xxx-0xx-000 Rev-1
>EP-CW< FRC 01LG

M2
0449

22

ST_LED1