

INTERTEK TESTING SERVICES

Internal photos

LS-S3420-USB




Individual C5021-USB from LS-S3420-USB

INTERTEK TESTING SERVICES

Internal photos

C5021-USB



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



LS-S3420



INTERTEK TESTING SERVICES


Internal photos

Same internal for LS-S3420-USB and LS-S3420




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 18010487HKG-001
FCC ID: EW780-H0CX-40
IC: 1135B-80H0CX40

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 18010487HKG-001
FCC ID: EW780-H0CX-40
IC: 1135B-80H0CX40



INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

