

**PHOTOS - TEST SETUP** 

Company: Itron

Product Name: ERG-7600-005


Report No.: ITRO67 - Test Setup Photos



Title: To: Serial #:

## 1. Test Setup Photographs

## 1.1.1. Test Setup



Digital Emissions ERG-7600-005, 1-18GHz Back


**Issue Date:** 23 July 2024 **Page:** 2 of 7



To: Serial #:



ERG-7600-005, 30MHz-1GHz Back



ERG-7600-005, 30MHz-1GHz Front

Issue Date: 23 July 2024

Page:

3 of 7




To: Serial #:

Title:



Spurious Emissions ERG-7600-005 1-18GHz Back



Spurious Emissions ERG-7600-005, 1-18GHz Front


Issue Date: 23 July 2024

**Page:** 4 of 7




To: Serial #:

## 1.1.2. Test Setup - RF#2 - Conducted



RF Conducted Test Setup 1



RF Conducted Test Setup 2

Issue Date: 23 July 2024

**Page:** 5 of 7



Title: To:

Serial #:

ITRO67 ERG-7600-05 Test Setup Photos

ERG-7600-005 deemed by Itron to be the worst case and covers the following models also. Please see Declaration of Similarity in reports:

ERG-7600-006 ERG-7600-010

**Issue Date**: 23 July 2024 **Page**: 6 of 7





575 Boulder Court Pleasanton, California 94566, USA Tel: +1 (925) 462 0304 Fax: +1 (925) 462 0306 www.micomlabs.com