

Internal photographs
Board Mounted in chassis




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore Amtech Technology Center
Model: AI1422E
Test #: 160802
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422E IntPho

S/N: 6073834
FCC ID#: FIHAI1422E
IC: 1584A-AI1422E
Date: August 30, 2016
Page 1 of 4

Top of Board all Shields removed




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore Amtech Technology Center
Model: AI1422E
Test #: 160802
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422E IntPho

S/N: 6073834
FCC ID#: FIHAI1422E
IC: 1584A-AI1422E
Date: August 30, 2016
Page 2 of 4

Bottom of Board




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore Amtech Technology Center
Model: AI1422E
Test #: 160802
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422E IntPho

S/N: 6073834
FCC ID#: FIHAI1422E
IC: 1584A-AI1422E
Date: August 30, 2016
Page 3 of 4

Main Shield cover removed



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore Amtech Technology Center
Model: AI1422E
Test #: 160802
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422E IntPho

S/N: 6073834
FCC ID#: FIHAI1422E
IC: 1584A-AI1422E
Date: August 30, 2016
Page 4 of 4