



Single Port



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup


SN's: 21104849, 21230053
FCC ID: FIHMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 1 of 7



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup

SN's: 21104849, 21230053
FCC ID: FIHMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 2 of 7




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup

SN's: 21104849, 21230053
FCC ID: FIHMPRXP90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 3 of 7


4 port



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup


SN's: 21104849, 21230053
FCC ID: FIHMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 4 of 7



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup

SN's: 21104849, 21230053
FCC ID: FIHMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 5 of 7



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup

SN's: 21104849, 21230053
FCC ID: FIHMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 6 of 7



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX45
PMN: MPRX
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX TSup

SN's: 21104849, 21230053
FCC ID: FIHMMPRXPT90V45
Test: 211025 IC: 1584A-MPRXR137V45
Date: November 9, 2021
Page 7 of 7