

January 11, 2000

FCC Part 15  
Washington DC  
Attention: Mr. Joe Dichoso

Reference: FCC ID G9H27730A  
Applicant: Thomson Electronics Inc.  
731 Confirmation Number: EA95652

Dear Mr. Dichoso:

In response to your E-mail to Mr. Grahame Watts on 12/20/99, attached are the information requested. Our responses are in bold and italic.

1) The RF safety exhibit is under review and any questions will be forwarded as soon as possible.

***No actions requested from us at this time.***

2) Some of the schematics did not convert properly. Please resent the schematics for the BASE RF, Handset RF and Base Line interface.

***See the following files.***

***BASE RF – 27730[Base RF].pdf***

***Handset RF – 27730[Hand RF].pdf***

***Base Line Interface – 27730[Base Tel].pdf***

3) Item #7 (bandwidth test) and # 10 ( output power) requested in the last correspondence were not submitted. Please submit them.

***See file “Telian1.pdf”***

4) Verify that all of the channels are used before repeating a channel.

***See file “UL2.pdf”***

5) Verify that there is no coordination of hopping sequences between two or more transmitters.

***See file “UL2.pdf”***

If you have any questions or comment, please feel free to contact me at 408 985-2400 x 32164 or [Timothy K. Lee@us.ul.com](mailto:Timothy.K.Lee@us.ul.com).

Sincerely,

Timothy Lee (Ext. 32164)  
Senior Project Engineer  
Engineering Services  
Underwriters Laboratories Inc.