



attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The Stanly Guard Inventory Control System – Object Tracking Device –
FCC ID: GDOICS311000, and label is so small that it cannot include the statement
specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)
"This device complies with Part 15 of the FCC Rules. Operation is subject to the
following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received,
including interference that may cause undesired
operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A,
Section 15.19 (a) (5) and this statement appears in a prominent location in the user
manual.

Please contact me if there is any information you may need.

Sincerely,

Irit Teerosh,

The Stanley Works Israel Ltd
19 Ha'Melacha st.
New Industrial Zone
Rosh Ha'Ayin, 48091
Israel

29th July, 2012