

**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001


**Photo # 7**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001






**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001


**Photo # 9**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001




**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 10**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001











**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 13**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001










**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 17**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001



**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 18**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001



**Annex 3 - Internal Photographs of the Equipment under Test**

Psion Teklogix Handheld Computer, Model 7530-RA1001


**Photo # 19**


FCC ID: GM37530RA1001  
IC: 2739A-RA1001




**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 20**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001









**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 24**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001



**Annex 3 - Internal Photographs of the Equipment under Test**  
Psion Teklogix Handheld Computer, Model 7530-RA1001

**Photo # 25**  
FCC ID: GM37530RA1001  
IC: 2739A-RA1001

