



INTERTEK TESTING SERVICES

Report No.: HK11080696-1
Sample No.: 1/2 (Docking)



Bandedge Plot – Pursuant to FCC Part 15 Section 15.249 Requirement