

**Honeywell International Inc**

Honeywell Scanning and Mobility  
9680 Old Bailes Road  
Fort Mill, SC 29707 USA

Date: **January/19/2015**

To whom it may concern:

Honeywell International Inc, hereby declares that Wi-Fi channels 12 and 13 for **Dolphin 75e** with model numbers, 75eL0N (with FCC ID: HD5-75EL0N) and 705eL00 (with FCC ID: HD5-75EL00) are disabled via Software driver. The SW driver will disable the channels and modify the power according to the part number which contains special field for regulatory domain purposes. This part number is flashed during manufacturing process.

The product respects all relevant provisions of FCC KDBs 594280 D01 Software Configuration Control v02r01 and 594280 D02 U-NII Device Security v01r01.

Sincerely,



Michael Robinson  
Phone: 315.554.6387  
Email: [michael.robinson3@honeywell.com](mailto:michael.robinson3@honeywell.com)