No. 65, Ku Dai Keng St., Hsichih, Taipei 221, R.O. C. No. 120, Lane 180, San Ho Tsuen, Hsin Ho Rd. Lung-Tan Hsiang, Tao Yuan County 325, Taiwan, R.O.C. Tel: 886-2-2646-2550 FAX: 886-2-26464641

Tel: 886-3-407-1718 FAX:886-3-407-1738

## Letter for supersede

Date: May 25th, 2010

Federal Communication Commission Equipment Authorization Branch 7435 Oakland Mills Road Columbia, MID 21046

FCC ID: HLZ-AR5B95

Model: AR5B95

## Gentlemen:

We would like to supersede 2 documents for the subject FCC ID.

It was granted on May 20th, 2010

Reason of Supersede: 1) Typos on page 1 Test Summary of SAR report.

2) Typos on page 28 of users manual.

According to page 21 and 22 test result summary of this report, the correct measurement unit should be W/kg, rather than W/g. The worst data was also indicated on the users manual page 28.

Sincerely,

Jim Chu/ Director

**International Standards Laboratory**