

No. 65, Ku Dai Keng St., Hsichih, Taipei 221, R.O. C.
No. 120, Lane 180, San Ho Tsuen, Hsin Ho Rd. Lung-Tan Hsiang,
Tao Yuan County 325, Taiwan, R.O.C.

Tel: 886-2-2646-2550 FAX: 886-2-26464641

Tel: 886-3-407-1718 FAX: 886-3-407-1738

Letter for supersede

Date: May 25th, 2010

Federal Communication Commission

Equipment Authorization Branch

7435 Oakland Mills Road

Columbia, MID 21046

FCC ID: **HLZ-RTL8191SE**

Model: **RTL8191SE**

Gentlemen:

We would like to supersede 2 documents for the subject FCC ID.

It was granted on May 20th, 2010

Reason of Supersede: **1) Typos on page 1 Test Summary of SAR report.**

2) Typos on page 28 of users manual.

According to page 21 and 22 test result summary of this report, the correct measurement unit should be W/kg, rather than W/g. The worst data was also indicated on the users manual page 2.

Sincerely,



Jim Chu/ Director

International Standards Laboratory