

Honeywell International Inc, FCC ID: HS9-51393SL, Assessment NO.: AN08T7590, Notice#1

Inbox
X

 from

tim.dwyer@ccsemc.com

[hide details](#) 10:08 PM (11 hours ago)

 Reply

to

Hsieh@etc.org.tw,

cc

tim.dwyer@ccsemc.com,

date

Feb 11, 2008 10:08 PM

subject

Honeywell International Inc, FCC ID:
HS9-51393SL, Assessment NO.:
AN08T7590, Notice#1

Dear Joe,

Review of this application is complete. Please reply to the following question.

Q1: 15.231(a)(1) and 15. 231(a)(2) require that a manually operated transmitter cease operation within 5 seconds of release of the manually operated switch and that an automatically activated transmitter cease operation within 5 seconds after activation. If this transmitter may be activated both manually and automatically, so it must comply with each requirement according to the method of activation. The requirements are stated in the test report, but there is no statement that the transmitter was evaluated to the requirements or that it complied. Please revise the test report or provide a separate statement regarding compliance with these requirements. Note that this requirement applies only to the 433 MHz transmitter operating under 15.231. and not to the composite transmitter operating at 2.4 GHz.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical Reviewer

 Reply

 Reply to all

 Forward

 from

Joe Hsieh <hsieh@etc.org.tw>

[hide details](#) 3:47 AM (5 hours ago)

 Reply

to

tim.dwyer@ccsemc.com,

cc

tim.dwyer@ccsemc.com,

date

Feb 12, 2008 3:47 AM

subject

Re: Honeywell International Inc, FCC
ID: HS9-51393SL, Assessment NO.:
AN08T7590, Notice#1

Dear Tim,

Attached please find the revise test report. This device is a manually device. The test result has added in the report. Please check. Thanks.

Best regards,
Joe
- Show quoted text -

 07-12-MAS-149-02_Test Report.pdf

378K

[View as HTML](#)

[Download](#)