

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 2. Bottom of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 3. Left Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 4. Right Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 5. Front of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 6. Back of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 7. EUT with Radio Module Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 8. Back of Radio Module Removed from PCB

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 9. Corner Reflector Antenna for Murata WIT2420

Manufacturer	Type	Gain	Connector
Mobilemark	Corner Reflector	+9.0	Reverse N-Type

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 10. Corner Reflector Antenna on EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420




Figure 11. Patch Antenna for Murata WIT2420

Manufacturer	Type	Gain	Connector
Murata	Patch	+6.0	MMCX

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 12. Patch Antenna on EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 13. Dipole Antenna for Murata WIT2420

Manufacturer	Type	Gain	Connector
Nearson	Dipole	+2.0	Reverse SMA

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 247
HSW-2420
4492A-2420
21-0174
July 1, 2021
Murata Electronics North America
WIT2420



Figure 14. Dipole Antenna on EUT