

Appendix D. SAR Test Setup Photos

<ZQ630 with Battery 3>

Body Exposure Condition



Front at 0mm



Back at 0mm



Back with Holster at 0mm

<ZQ630 with Battery 3>

Hand Exposure Condition



Front at 0mm



Back at 0mm



Left Side at 0mm



Right Side at 0mm



Bottom Side at 0mm



Top Side at 0mm



Back with Holster at 0mm