



**MOTOROLA**

**Date:** October 22, 2007

**Subject:** Request for additional information regarding FCC ID: IHDP56HF1

**Reference:**

Correspondence Reference Number: IHD7709  
Confirmation Number: 708060709  
Date of Original Email: October 22, 2007

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Mobile Device Business  
Libertyville, Illinois

Questions and responses follow:

1. FCC ID Label in Exhibit 1 shows incorrect FCC ID. Please revise.

**Response:** Please refer to the revised exhibit 1.

2. Operational Description does not include 850/1900 Band operational description, only 900/1800. Please clarify.

**Response:** This transceiver operates in the 850 GSM and 1900 PCS bands only. Please refer to the revised exhibit 12.

3. Please clarify if the device is capable of GPRS. If so, please specify the maximum number of transmitting slots possible, and include updated Body SAR data, as necessary.

**Response:** This device does not operate in GPRS mode. Only one transmitting time slot (1:8) is possible.

4. 1800 MHz SAR Recommended Target should be 37.5 W/kg instead of 38.1 W/kg (Page 6, Exh. 11) according to the Certificate for System Performance Check Targets on Page 44, Exh 11 of the SAR Report. Please revise.

**Response:** Please refer to the revised exhibit 11.