



MOTOROLA

Date: December 1, 2008

Subject: Request for additional information regarding FCC ID: IHDP56JC1

Reference:

Correspondence Reference Number: IHD81107
Confirmation Number: 811261107
Date of Original Email: December 1, 2008

Prepared by:


Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:


1. Please provide details regarding the changes, photographs, and also justification of why only one frequency band was tested.

Response: Please refer to the following details of the changes. The submitted test report includes results from both bands (only 850 MHz degraded).


RF Change 1: Antenna Match Layout Change



- Antenna matching parts were pulled inwards (away from the periphery of the board) to help some issues with ALT drop testing




RF Change 2: Main Antenna Match



Original

- L357 3.3 nH (no change)
- C375 22 pF (no change)
- L355 from DNP to 15 nH
- C376 22 pF (no change)



Class II

2. Please also provide justification for SAR.

Response: SAR was tested, but since there was no degradation, new data is not submitted.