



MOTOROLA

Date: October 22, 2008

Subject: Request for additional information regarding FCC ID: IHDP56JM2

Reference:

Correspondence Reference Number: IHD80849
Confirmation Number: 809090849-51
Date of Original Email: October 14, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Please submit an Operational Description for the licensed transmitter and Class B peripheral (PCE and JBP)- please note that the same Operational Description may be used for both of these.

Response: [Please refer to the Operational Description attached. We also uploaded the file on the PCTEST website as well.](#)

2. Please submit an Operational Description for the BT transmitter (DSS).

Response: [Please refer to the Operational Description attached.](#)

3. Please submit a Key Feature List for the EUT, including the FCC ID, model number, and air interfaces, etc., for use in HAC compliance counts.

Response: [Please refer to the revised Exhibit 2 attached.](#)

4. Page 4 of HAC Report Exhibit 6B-1 indicates H-field probe is out of calibration. Please clarify.

Response: [Please refer to the revised HAC report attached.](#)

5. PMF plots for 1730 MHz are missing from HAC Report Exhibit 6B-1, Section A.1.2. Please provide.

Response: [Please refer to the revised HAC report attached.](#)