



MOTOROLA

Date: Nov. 23, 2009

Subject: Request for additional information regarding FCC ID: IHDP56KC4

Reference:

Correspondence Reference Number:	IHD91359
Confirmation Number:	911091359-62
Date of Original Email:	Nov. 17, 2009

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Please provide an explanation as to why the MPR does not appear to be implemented in HSPA mode per 3GPP2 according to Page 8 of the EMC and SAR Report.

Response: [Please refer to the revised SAR report submitted online.](#)

2. Please reconcile differences in WLAN powers on Page 5/43 in Exhibit 6A3; Pages 14-16 in Exhibit 6A5; and SAR report WLAN powers.

Response: [Please refer to the revised Exhibit 6A3 & SAR report submitted online.](#)

3. Probe Calibration Certificate for ES3DV3 SN:3180 is not the same probe as that used for SAR tests. Please update.

Response: [Please refer to the revised SAR report submitted online.](#)

4. The operational description provided is missing GSM850 and WCDMA II and V operations in the descriptions. Please update.

Response: [Please refer to the revised operational description EX12 submitted online.](#)