



**MOTOROLA**

**Date:** December 14, 2009

**Subject:** Request for additional information regarding FCC ID: IHDP56KX1

**Reference:**

Correspondence Reference Number: IHD91367  
Confirmation Number: 911091367  
Date of Original Email: December 3, 2009

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Mobile Device Business  
Libertyville, Illinois 60048

Questions and responses follow:

1. Please provide a detailed Bluetooth block diagram including the values of all clocks/oscillators.

**Response:** [Please refer to the revised BT block diagram on EX04 submitted online.](#)

2. The Exhibit 12 operational description includes Cellular band GSM and UMTS features of the Snapper TD (MT710). Please confirm that these are not implemented in the EUT.

**Response:** [Cellular band GSM and UMTS are not implemented in this EUT. Please refer to the revised Operational Description EX12 submitted online.](#)

3. Please provide the Bluetooth antenna peak gain.

**Response:** [Please refer to the revised BT report EX6A1 submitted online to address the antenna gain issue.](#)

4. Please change the results of the ERP test on page 4 to N/A in the Part 24 report (Exhibit 6).

**Response:** [Please refer to the revised EMC report EX06 submitted online.](#)