

## Description of Permissive Change

This report is prepared for FCC class II permissive change. The differences compared with the original are changing HW version, SW version and modifying antenna.

HW change list as below.

- For Motorola security function
- For ESD solution with +/- 15KV
- For SMT solder issue
- For touch panel sequence correction
- For TDMA noise
- For changing receiver
- For Motorola pre-charge mode
- For Transceiver TX/RX matching
- For Antenna matching change

SW version changed from: 7S82070000-002-R1J. to Kingfisher\_G\_07.1B.00R\_S.