



**MOTOROLA**

**Date:** June 26, 2008

**Subject:** Request for additional information regarding FCC ID: IHDP6JL1

**Reference:**

Correspondence Reference Number:	IHD80446
Confirmation Number:	805160446-48
Date of Original Email:	June 24, 2008

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Mobile Device Business  
Libertyville, Illinois 60048

Questions and responses follow:

1. The Cover Letter lists EDGE operation, but this is not supported elsewhere in the application. Please clarify, and revise as necessary.

**Response:** [It was a typo to put "EDGE" there. Please refer to the revised cover letter EX13.](#)

2. Please resubmit the user's manual, including the statements required by Sections 15.19, 15.21 and 15.105, as well as the body-worn RFX warning statement.

**Response:** [Please refer to the revised user's manual EX08.](#)

3. Please correct the max SAR levels listed in the user's manual.

**Response:** [Please refer to the revised user's manual EX08.](#)

4. FYI: it appears that, in the BT radiated emission test report, the noise floor may exceed the limit at high frequencies. This must be addressed in the future.

**Response:** [Understood and will address in the future.](#)