



MOTOROLA

Date: June 18, 2009

Subject: Request for additional information regarding FCC ID: IHDP6KL1

Reference:

Correspondence Reference Number:	IHD90570
Confirmation Number:	905070570-2
Date of Original Email:	June 17, 2009

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Please include RF Warning for Body-Worn Exposure conditions (i.e. spacing for Body-worn compliance).

Response: [Please refer to the revised user's manual submitted online. The required info is on page 7.](#)

2. Power drift is greater than 5% for BT Body SAR per the plot. In the future please ensure drifts are within 5%.

Response: [Noted.](#)

3. Page 6 of Exhibit 6 indicates an incorrect power for the mid channel. Please amend.

Response: [Please refer to the EMC supplement Response attached.](#)

1. Schematics indicate presence of PCS Bands and WLAN. Please clarify for this application.

Response: [This device does not have PCS bands & WLAN operations.](#)

2. Exhibit 13 says “PCS”. Please clarify or amend.

Response: [Please refer to the revised cover letter attached.](#)

3. Please submit a more detailed Bluetooth operational description.

Response: [Please refer to the revised Operational Description submitted online.](#)