

Compliance Certification Services Inc.

Dec. 26, 2011

FCC ID : IHDP6MD2

Technical Justification Letter

To Whom It May Concern:

1. SF600 FCC ID : IHDP6MD1 has BT 4.0 module in left ear phone which has been disabled by software.
SF600 FCC ID : IHDP6MD2 without Bluetooth 4.0 module in left ear phone.
2. As the right ear head phone containing the active Bluetooth IC is the exact same electrical hardware in both versions of the device we are submitting test report:T111110303-RP1 for testing performed on the IHDP6MD1 (Bluetooth IC installed in the left ear phone but software disabled) , after the technical valuation we demonstrate compliance for the IHP6MD2 (left ear phone Bluetooth IC depopulated).



Signature

Miller Lee / Manager-WuGu BU