



MOTOROLA

Date: November 4, 2003

Subject: Request for additional information regarding FCC ID: IHDT56DH1 (Cellular/PCS transceiver)

Reference:

Application Received: 10/10/2003
Correspondence Reference Number: 231103A.IHD
Confirmation Number: TC3259
Date of Original Email: 10/30/2003

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Personal Communications Sector
Libertyville, Illinois

Questions and responses follow:

1. Regarding the additional SAR plots that you submitted in response to our original email, a number of them have values that differ from those listed in the Tables of highest SAR values, on pages 8 and 9. Please correct the values listed in the Tables to the values listed below, so that they correspond to the data plots.

CDMA Channel 384 right tilt antenna extended should be corrected to 0.234
CDMA Channel 384 right tilt antenna retracted should be corrected to 0.215
PCS Channel 600 right tilt antenna extended should be corrected to 0.213
PCS Channel 600 right tilt antenna retracted should be corrected to 0.288
CDMA Channel 384 body-clip against body antenna extended should be corrected to 0.213

Response: Please refer to the supplemental SAR report submitted on November 4, 2003.

2. We note that several of the recently submitted SAR plots list values for the conductivity and dielectric constant that differ from the values listed in the Table on p.4. Please address.

Response: Please refer to the supplemental SAR report submitted on November 4, 2003