



MOTOROLA

Date: June 4, 2007

Subject: Request for additional information regarding FCC ID: IHDT56GK1

Reference:

Correspondence Reference Number:	IHD7417
Confirmation Number:	705180441
Date of Original Email:	June 1, 2007

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

Questions and responses follow:

1. Please provide a detailed description of the proposed modifications.


Response: Second source vendors have been added for following parts:

1. Shielding Case 2nd source
2. Shielding Case Frame 2nd source
3. Shielding Case Cover 2nd source
4. Antenna with thin plate
5. Spring Contact Flip 2nd source
6. Metal Patch 2nd source
7. FPC 2nd source
8. Vibrator with full coverage of Rubber(follow C168 ECN)

Please refer to the **Figures 1 – 4** following the questions and response section (pages 2 and 3).

2. Please submit test set up photos.

Response: Please refer to exhibit 7 attached: "GK-EX7.pdf"




MESCY23006B Shielding Case Mic


MESCY23005C Shielding Case Frame NWinG SCY

Figure 1


MESCY23004B Shielding Case Cover NWinG SCY



Antenna with thin




MESCY22005B Metal Patch NWinG SCY




MESCY22004B Spring Contact Flip NWinG SCY

Figure 2



FPC 2nd

Figure 3



Vibrato

Figure 4