



MOTOROLA

Date: February 12, 2007

Subject: Request for additional information regarding FCC ID: IHDT56HB1

Reference:

Correspondence Reference Number: IHD7065
Confirmation Number: 702020065-67
Date of Original Email: February 9, 2007

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

1. Please submit statement in the users manual for compliance to Part 15.21.

Response: The statement for Part 15.21 was added to the User's Manual. An Exhibit 8 replacement was uploaded to the PC Test website on 02-12-2007 and is also attached to this letter.

2. Several equipments in the EMC Report (Exhibit 6) have calibrations expiring before the completion of the tests. Please explain.

Response: All testing was performed using equipment that was within calibration at the time that the test was performed. No equipment listed in the equipment table was used after the specified calibration due date. If, during the course of product testing, a piece of equipment went out of calibration and that piece of equipment was needed to complete product testing, a similar piece of calibrated equipment was substituted. If a substitution was made, that new piece of equipment would be listed in the equipment table along with the piece that was removed from service.

3. Operational Description (Exhibit 12) states GPRS and EDGE Class 12; however SAR Report (Exhibit 11) Page 2 describes only two slot GPRS and single slot EDGE capability and from the SAR plots was tested as a Class 10 device. Please clarify.

Response: Per section 6.2, paragraph 5 of the SAR report, the device is mutlislot capable up to four uplink timeslots and was tested in the worst-case condition with respect to time-average output power. This worst-case condition exists with the device transmitting with two uplink timeslots. An updated report is provided to correct the table on page 2. An Exhibit 11 replacement was uploaded to the PC Test website on 02-12-2007 and is also attached to this letter.

4. Page 92 in the Users Manual (Exhibit 8) does not have the correct SAR values for this application. Please update.

Response: The SAR values were corrected. An Exhibit 8 replacement was uploaded to the PC Test website on 02-12-2007 and is also attached to this letter.