



EMC TEST SETUP PHOTOS




EMC Report #19594-2, AC Line - Part 15



EMC Report #19594-2, Part 15, PC Peripheral



EMC Report #19594-2, Antenna - Substitution



EMC Report #19594-2, Tx Radiated

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19600-1F**



Figure1: Front of Phone



Figure2: Back of Phone

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19600-1F**



Figure3: Phone Open



Figure4: Phone Against the Flat Phantom

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19600-1F**



Figure5: Phone Against the Head Phantom (Cheek Touch)




Figure6: Phone Against the Head Phantom (15° Tilt)

APPENDIX A

PHOTOS


FCC ID: IHDT56HL1 UL EMC TESTS



Radiated Emissions
X-Axis



Radiated Emissions
Y-Axis



Radiated Emissions
Z-Axis