



## Motorola EMC TEST SETUP PHOTOS




Motorola EMC Report #19881-1, AC Line - Part 15



Motorola EMC Report #19881-1, Part 15, PC Peripheral



Motorola EMC Report #19881-1, Antenna - Substitution



Motorola EMC Report #19881-1, Tx Radiated

**Appendix 6**  
**(PULLED FROM FCC EXHIBIT 11)**  
**Photographs of the device under test**



Figure 1 – Front of Transceiver



Figure 2 – Back of Transceiver (Showing Standard and Extended Battery Doors)




Figure 3 – Transceiver against head, Cheek Touch position



Figure 4 – Transceiver against head, Cheek Touch position




Figure 5 – Transceiver against head, 15° Tilt position



Figure 6 – Transceiver against head, 15° Tilt position



Figure 7 – Transceiver against body, Back of Phone 15 mm from Phantom position



Figure 8 – Transceiver against body with Pouch accessory