



MOTOROLA

Date: May 20, 2008

Subject: Request for additional information regarding FCC ID: IHDT56JP1

Reference:

Correspondence Reference Number: IHD80244
Confirmation Number: 803260244-46
Date of Original Email: May 19, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. It appears that the RF shields were removed from the photos of the front side of the pcb, but not on the back side of the pcb. Please submit photos of both sides of the pcb with all shields removed.

Response: [Please refer to the revised Exhibit 09 attached.](#)

2. Please describe the Bluetooth antenna, and address Section 15.203.

Response: [The BT antenna is a fixed internal antenna with gain of -4.9 dBi, which meets the antenna requirement stated in Section 15.203.](#)