
From: LI LILLIAN-WNCK38
Sent: Monday, June 23, 2008 12:44 PM
To: Stephen S. Liu (PCTEST)
Subject: RE: Question Regarding FCC ID: IHDT56JR1

Hi Steve,

Please find our response below&attached and let us know if you have any further questions.

1. Regarding your response to Q.11, although an RF Emissions scan is still required in T-coil mode (centered over the T-coil) per Sec. 4.4, the T-coil rating is independent of the Clause 4 evaluation, as stated in Section 7.3.3. Therefore, the T rating should be T4. Please update the T-coil Report.

Response: Please refer to the updated report attached with respect to your response.

2. Regarding your response to Q.4, please clarify the cover letter to say GSM/WCDMA instead of GSM/CDMA.

Response: Please refer to the revised cover letter attached.

Thanks!

*Lillian Li
Certification and Approvals
Product Safety and Compliance
Motorola Libertyville
847.523.8825 Office*

From: Stephen S. Liu (PCTEST) [mailto:steve@pctestlab.com]
Sent: Friday, June 20, 2008 12:27 AM
To: LI LILLIAN-WNCK38
Cc: Bachler Andrew-WLAB00; Patel Ketan-WKFT38; 'PCTEST - Gregory Czumak'; 'PCTEST - Randy Ortanez'; 'PCTEST - Courtenay Geraghty'; 'PCTEST TCB'
Subject: RE: Question Regarding FCC ID: IHDT56JR1

Hi Lillian,

Thanks for your responses.

1. Regarding your response to Q.11, although an RF Emissions scan is still required in T-coil mode (centered over the T-coil) per Sec. 4.4, the T-coil rating is independent of the Clause 4 evaluation, as stated in Section 7.3.3. Therefore, the T rating should be T4. Please update the T-coil Report.

Response: Please refer to the updated report attached with respect to your response.

2. Regarding your response to Q.4, please clarify the cover letter to say GSM/WCDMA instead of GSM/CDMA.

Response: Please refer to the revised cover letter attached.

Best Regards,
Steve