



EMC TEST SETUP PHOTOS



EMC Report #22874 AC Line - Part 15



EMC Report #22874 Part 15, PC Peripheral



EMC Report #22874 Antenna - Substitution



EMC Report #22874 Tx Radiated