

Motorola Mobility LLC.

222 W, Merchandise Mart Plaza, Chicago IL 60654 USA


Product Equality Declaration

We, Motorola Mobility LLC, declare on our sole responsibility for the product as below:
The differences between EMEA DS and previous as below:


- HW section
- Add the following components suppliers below

Object	Previous 711913	Current 761213
Antenna_Switch(SP4T)	SKYWORKS: SKY19245-686LF	INFINEON: BGSA14GN10

Previous 711913



Current 761213



Previous: Manual to remove SAR Sensor Chip and SAR Sensor shrapnel;

Current: Optimizing the BOM patch and removing the Sar sensor and its matching circuits.

These changes have no effect on RF.

Except listings above, the others are all the same.

Should you have any questions or comments regarding this matter, please have my best

Lin BiaoChun

Contact Person: Lin BiaoChun

COMPANY: Motorola Mobility LLC.

Tel:86-18150396560

E-Mail: Linbc@lenovo.com