



MOTOROLA

Date: August 21, 2003

Subject: Request for additional information (FCC ID: IHDT6DL1)

Reference:

Applicant Received:	8/7/2003
Correspondence Reference Number:	230821.IHD
Confirmation Number:	TC3193
Date of Original Email:	8/21/2003

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Personal Communications Sector
Libertyville, Illinois

1. The antenna gain in AMPS mode and TDMA appears to be different. Please clarify.

Response: In the AMPS mode only, additional power level control is applied whenever the rf signal is directly connected to the antenna.

2. Please provide the following missing documents:

- a) Exhibit 1 – FCC ID Label and Location
- b) Exhibit 3 – External Photos
- c) Exhibit 9 – Internal Photos
- d) Exhibit 10 – Parts List and Tune Up
- e) Exhibit 13 – Cover (Confidentiality) Letter

Response: The exhibits listed above are resubmitted on 8-21-03.